

# Plastic Pipe Issues in the Eastern Region

Gary Kenny  
Maine Public Utilities Commission

New England Pipeline Safety Seminar  
Mt. Snow, Vermont  
October 21, 2015

# The Issues

- Butt Fusions
- Electrofusion
- Mechanical Tees
- Installation by Horizontal Directional Drilling
- Improper Pipe Handling
- Exposed Plastic Pipe

# Butt Fusions

## Inadequate Qualification and Resulting Poor Quality Joints


- A 2014 investigation, in New York State, revealed that six companies were not destructively testing hydraulic butt fusion samples during the qualification process [NY Rule and §192.285(b)(iii)].
- When requalified, 91 workers with one company failed the destructive testing module. This may impact over 800,000 fusions made back to 2002.

# Butt Fusions (Continued)

- As of May 2015, 173 in-service fusions, of that company, were examined. Of those, 72 failed visual inspections. Of those, 63 were destructively tested and eight failed.
- When all companies are considered, there may be nearly one million in-service fusions impacted.
- In May 2015 the NY PSC Ordered an extensive remediation program.



# Questionable Beads



# Butt Fusions (Continued)

- Lack of Understanding of Interfacial Fusion Pressure (IFP)
  - IFP is the allowable range of pressure that's required between the faces of the pipes being joined, during the fusion process, to result in an adequate fusion;
  - IFP is constant for all sizes and wall thicknesses of pipes of the same type; and
  - The gauge pressure on hydraulic fusion machines varies with:
    - The pipe diameter and wall thickness;
    - The hydraulic piston area; and
    - The hydraulic pressure (drag) required to move the pipe being joined.



# Hand Pump Hydraulic Fusion Machine



# Hydraulic Pressure Gauge



# Butt Fusions

- Inadequate Cooling Time for Rough Handling

This is a problem noted with all types of fusion. It's sometimes not recognized by field personnel:

- That Rough Handling requires additional cooling time after the pipe may be removed from the clamps; and
- What constitutes Rough Handling?
  - Pulling, Installation in Trench, Etc.

# Electrofusion

- Couplings
  - Inadequate Preparation
    - Conventional
    - Tie-In Applications
  - Inadequate Cooling Time for Rough Handling
  - Alignment – If you need to use the backhoe bucket to align the pipes, the electrofusion will likely fail.



# Coupling – Left End





# Coupling – Right End



10.05.2015 12:56



# Fusion Failed After Equipment Used to Align Pipes



# Coupling Preparation at Tie-Ins

- Where the coupling is slid entirely over the end of one pipe;
- That pipe must be prepared over the entire length of the coupling.

# Electrofusion Couplings

Is the pipe adequately prepared for this coupling?



It Depends!

# Electrofusion

- Tees
  - Improper Clamps
  - Inadequate Preparation
  - Inadequate Cooling Time for Rough Handling



# A Tee that Failed During Pressure Testing





# Location of Tee Failure



# Sidewinder – Not Approved for Electrofusion Tees



# Mechanical Tee - Installation

Depend on the threads of the cutter's sleeve to hold them on the main





# Horizontal Directional Drilling

- Cross Bores
- Inadequate Weak Links
- Lack of Pull Through to Inspect for Damage
- Not Knowing What Else is Underground

# Cross Bore of a Sewer Lateral





# Cross Bore of a Culvert





# Damage from a Mechanical Snake



08.18.2014 15:13

# Weak Link (Breakaway)





# Pipe in a Casing?





# No, a Gas Main Installed by HDD in a Drain Line



# Improper Pipe Handling

- Dragging Pipe
- Lack of Care when Placing Pipe in Ditch



# Damaged Beads Are an Indication to Look Closer



08.14.2013

# This is What You May Find



08.14.2013



# Pipe Was Dragged After Fusion



# Exposed Plastic Pipe

- Most Often Found on Propane Systems
  - In tank domes
- Plastic Pipe Used for Regulator Vent Piping
  - Must be PVC that's rated for UV exposure – gray electrical conduit



# Exposed PE Pipe in a Tank Dome



# How Do These Issues Occur?

The Cause of Plastic Pipe Issues is \_\_\_\_\_.

- a. lack of an adequate qualification process
- b. lack of adequate training for operator and contractor personnel
- c. failure to follow procedures
- d. lack of adequate inspection
- e. rogue employees
- f. All of the above



# What Can Be Done To Prevent These Issues?

- Better Training
  - Mandatory for all, not just for those that fail the OQ test.
  - Minimum experience levels for trainers.
- Third Party (Independent) Qualification Examiners
  - Proctoring of written and/or on-line tests.
  - Individual hands-on testing.
- More Thorough Inspection by Operators

# Distribution Integrity Management Program (DIMP)

- If there is a potential that the threat of inferior pipe joining may exist, it must be included as a threat in the DIMP written plan; however
- The inclusion of inferior pipe joining in the DIMP plan IS NOT an alternative to removing all known defects from new construction!



# Suggested References

- Keynote speech given by MPUC Chairman, Mark Vannoy, at the October 8, 2015 conference, *Natural Gas: Energy for Maine's Future?!*
- May 15, 2015 NY PSC Order Requiring Local Distribution Companies to Follow and Complete Remediation Plans as Modified by this Order and to Implement New Inspection Protocols



# Questions



Thank You!