Cross-Bore Inspection Programs

Do you know the risks?

Nathan Dore

Gas Pipeline Safety Inspector Maine Public Utilities Commission

Discussion Topics

- Warning Signs Advisories and Incidents
- Basic Elements
- Performance-Based Program Quality Safety Culture
- Program Evolution Scenario Lite What Risks Have You Considered?
- A Common Effort

August, 1976 – Kenosha, Wisconsin

 Log P-GT Der TDT Par P-16-13 Hard 16

 NATIONAL TRANSPORTATION SAFETY BOARD WASHINGTON, D.C.

 FOR RELEASE:
 6:30 A.M., E.S.T., NOVEMBER 12, 1976

 (202)
 426-8787

 Forwarded to:
 Mr. C. S. McNeer President

 Wisconsin Natural Gas Company 233 Lake Avenue Racine, Wisconsin 53401
 SAFETY RECOMMENDATION(S) P-76-83 through P-76-86

At 8:53 a.m., on August 29, 1976, an explosion and fire destroyed a house at 6521 20th Avenue in Kenosha, Wisconsin. Two persons were killed, four persons were injured, and two adjacent houses were damaged. The destroyed house was not served by natural gas. However, natural gas, which was escaping at 58 psig pressure from a punctured 2-inch plastic main located 39 feet away, had entered the house through a 6-inch sewer lateral. The gas was ignited by an unknown source. After the accident, the National Transportation Safety Board's investigation disclosed that the gas main had been installed by boring through the bottom of the sewer tile; the gas main was perpendicular to the sewer tile. 1/

In July 1975 the Wisconsin Natural Gas Company (Wisconsin) employed a contractor to construct the gas main parallel to the curb on 20th Avenue. The contractor used a combination of open trenching and pneumatic boring techniques to install the main.

Recommendations included:

- Inspect other known close proximities, and correct deficiencies
- Examine records for additional unknown close proximities, review blockage complaint records
- Revise construction standards to result in more accurate facility locates
- Inform, advise, and train personnel

February 2010 - St. Paul, Minnesota



Photo credit: Pioneer Press

MNOPS AL-01-2010

MINNESOTA DEPARTMENT OF PUBLIC SAFETY



State Fire Marshal and Pipeline Safety

444 Cedar Street • Suite 147 • Saint Paul, Minnesota 55101-5145 Phone: 651.201.7230 • Fax: 651.296.9641 • TTY: 651.282.6555 www.dps.state.mn.us

Alert Notice-MNOPS AL-01-2010 to Natural Gas Pipeline Operators

Preventing Sewer Service Lateral Cross Bores: Acceptable Practices and Documentation Requirements

Alcohol and Gambling Enforcement

ARMER/911 Program

Bureau of Criminal Apprehension

Driver and Vehicle Services

Homeland Security and Emergency Management

Minnesota State Patrol

Office of Communications

Office of Justice Programs

Office of Traffic Safety

State Fire Marshal and Pipeline Safety



May 10, 2010

Purpose:

Date:

The purpose of this Alert Notice is to provide guidance for gas pipeline installers on acceptable installation practices and documentation requirements when installing gas mains and services.

Background:

The Minnesota Office of Pipeline Safety (MNOPS) is now aware of at least 155 instances in Minnesota where gas pipelines were inadvertently installed through privately owned sewer service laterals due to trenchless construction techniques; MNOPS believes there are probably more.

The majority of these "cross bores" were found by plumbers while cleaning sewer service laterals. Since 2000, six gas lines have been punctured by sewer cleaning contractors. On three occasions, the gas ignited, resulting in significant injuries and property damage.

The following Acceptable Practices and Documentation Requirements were developed following a review of industry white papers, a review of previous cross-bore incidents, and discussions with gas distribution pipeline operators on widely available methods and practices.

- Summary of local problem
- Reactive attempt by regulatory body to address public safety concern
- Outlined acceptable installation practices and documentation requirements for new construction
- Did not address legacy issue directly
- Promotes data sharing

Adequate response?

 2012 GTI "Cross Bore Best Practices" interviewed 23 LDCs

- 83% had or planned to include cross-bore risks as part of DIMP
- 56% had or were developing a legacy program
- 30% had no legacy program and were not exploring the option
- 17% made a process change to facilitate inspection or discovery of cross-bores

Adequate response?

- 2013 PHMSA/NAPSR survey
 - 38% responding states had formal directives/regulations directed towards avoiding cross-bore potential
 - 69% responding states had damage prevention regulations regarding boring
 - Of this 69%, 42% required sewer laterals to be marked

Must / should your company have a CBSIP?

"If no alt reasons, its is of treamables sated in a latin since inclusion withous tooking brains under doin the distribution of a later of a later of the set of the

GTI Best Practices Guide, 2012 PHMSA DIMP FAQ C.4.b.3

DIMP Implementation Keys

- Appropriate
 Megration
 Flexible eno
 Design and
 - Public Awa

elements



Emissions Quantification Data								
Segment ID	Segment Rank	Emissions Rate (SCFH)	Emissions range (confidence)	Segment Length (ft)	Emissions Factor (SCFH/ft)	Estimated # of leaks	# Leaks/ft	Emissions Rate / Leak
-4	1	7.0	4 - 16 SCFH (90%)	1579	0.0044	5	0.0032	1.14
1	2	5.1	2 - 8 SCFH (90%)	3090	0.0017	5	0.0016	1.0
3	3	2.4	1 - 4 SCFH (90%)	2535	0.001	4	0.0016	0.6
2	4	1.5	0.5 - 2 SCFH (60%)	2514	0.0006	1	0.0004	1.5



Figure 2. EQ report data table and map for pipeline replacement

Some Basic Benefits to CBSIP

- Increase system knowledge / improve records
- Improve system integrity
- Avoid the cost of catastrophes

 Life/Property, Damages, Brand Reputation
- Regulatory Compliance
- Proactive program offers benefits over emergency response
 - Planning, resource allocation, engineering

Basic Program Outline

Cross-bore Avoidance Program
 – New Construction

Cross-bore Inspection/Remediation Program
 Legacy Installations



Basic Program – New Construction

- Adequate project planning
 - Cost/Benefit of Using Trenchless Methods
 - Available Sewer System Records
 - Private Utilities/Homeowners Contacted along with 811
 - Establish Level of Confidence in Records / Locating Method
 - Establish Tolerance Zone for Mandatory Exposure and Observation

Basic Program – New Construction

Location Methods

Measurement Calculation Visual + Tolerance Camera Proximity / DNE SNT



Basic Program – New Construction

Confirm Accuracy of Locating Equipment

Utility Post-Inspection



Basic Program – Legacy Inspections

 Actual Field Methods Similar to New Construction

- <u>Risk Assessment and Evaluation</u>
 - Setting Project Scope
 - Information Gathering
 - Project Validation (QA/QC) and Oversight

Basics - Other Program Elements

 Remediation Procedures Utility-Specific



- Emergency Response Integration
- Incorporation of Records / System Knowledge

Basics - Public Awareness

 Outreach to homeowners and service professionals

Outreach to public w/o gas service adjacent to trenchless installations

Public Service Messages to wide audience

Basics – Procedures and Personnel Training

- Design/Engineering
- Operations/Maintenance
- Emergency Response/Dispatch
- Construction Personnel
- Contractors
- Inspection/QA/QC



Establishing Culture

- Top-down approach includes:
 - Universal commitment at all levels
 - Promote sharing and engagement
 - Broadcast values consistently
 - Accountability
 - Incentivize buy-in
- Program must be:
 - Integrative
 - Accessible / Approachable at all levels
 - Useful
 - Self-Informed by Meaningful Metrics
 - Focused on achieving results



Evolution of Safety Programs



Federal Aviation Administration, "Safety Management System"

- Mature programs within performance based requirements follow a model of continuous improvement
- This model has analogs to the sophistication of CBSIPs from Response-based processes (reactive) to data-driven inspection programs (predictive)

Scenario - Getting Started

49 CFR § 192.1007

What are the required elements of an integrity management plan (distribution operators)?

- a) Knowledge
- b) Identify threats
- c) Evaluate and rank risk
- d) Address risks
- e) Measure performance
- f) Periodic improvement

Getting Started


Scenario:

Company hired a contractor to install ten miles of 4" MDPE plastic in moderately dense residential portions of service territory in 1990s. Contractor drilled in pipe where possible to save on restoration costs.

Cross bore prevention techniques included consistent use of 811, company inspectors over construction crews, sewer manhole measurements where available to confirm sewer district markouts. Sewer records inconsistent, sewer system vintage varied.

Scenario - Getting Started

- "Leaks by cause" have never included "other outside force damage" via plumbing service since DIMP implementation in 2011
- No recorded instances of cross-bores company-wide



Scenario - Initial Posture

- Cross-bore risk mentioned in DIMP documents

 low risk, no additional measures to address
 issue
- Review of construction records to determine areas of system installed via trenchless methods
- Discuss implementing new construction practices

Scenario – Nearby Event

- Neighboring operator selfreports several cross-bores to regulatory agency during main replacement project
- Regulatory agency issues advisory bulletin
- Topic is covered at annual regulatory safety conference



Scenario - Basic Program Developed

Leadership Interest In:

- Legacy Inspection Program for Target System
- New Construction Procedures Established
- Personnel Training
- Basic Public Awareness Campaign
- Emergency Response Protocol

Program Maturity

- Team Membership
- Recordkeeping Practices
- Outreach and Information Sharing
- Risk Based Approach to Records Review
- Self Assessment

Program Maturity – Legacy Records


- Trenchless installation methods used?
 - Era
 - Contractors
 - Personnel on Site
 - Soil Type
 - Density of Below-Grade Obstructions
 - Depth
 - Material Type
 - Type of Structures

Program Maturity – Legacy Records

- Other Information Sources
 - In-house SMEs
 - Public records
 - Foreign utility records
 - Homeowners/Proprietors
 - Contractors
 - Previous Response Logs (Pre-Awareness)

Program Maturity – Legacy Records

- Other Information Sources Could Reveal:
 - Depth of Utilities
 - Unrecorded Branch Services
 - Previous Structures
 - Conflict Types Not Considered
- Establish Criteria for Confirmed Clearance
 - May Require Site Inspection



Feedback

- Confirmed cross-bore data points used to inform process
 - Analysis gaps
 - Review for system-wide commonalities
 - Right-size Program
- QA/QC Process
 - Records and field verifications
 - Findings used to expand quality reviews



GIS Benefits

GIS System Integration

- Monitor program status vs. risk priority
- Complex queries and iterative analysis
- System design
- Improved response
- Integrate data from multiple process including CBSIP




Image: Cross Bore Safety Association/Hydromax

Common Interests

- Sewer Departments
 - Cleaning and Inspection
 - Locating Data
- Regulatory Agencies

 Sharing Best Practices
 - Self-Reporting



- Damage Prevention Stakeholders
 - Reducing Utility Damages
 - Mutual Planning and Awareness
 - Public Awareness Campaigns

What's Going On?

- Call Before You Clear™
 - Using Existing One-call Foundation
- Comprehensive Public Awareness Campaigns
- New Technology Developments
- Stakeholder Working Groups
- Cross-Bore Bounty
- Industry Organizations



Thank You!

Maine Public Utilities Commission Gas Safety Program www.maine.gov/mpuc/natural_gas/natural_gas_safety

Thanks To: UGI Utilities, Inc., Southwest Gas Corporation, Cross-Bore Safety Association, NAPSR, Gas Technology Institute, Summit Utilities, Inc., Hydromax USA, Pro-Pipe, PHMSA